

## FANTOME

### Non-routine maintenance history (excluding annual hull repainting, antifoul, etc.)

#### Previous ownership

- 1987 Re-planking and other works, following professional survey
- 1988 New forepeak hatch cover  
New no.2 jib
- 1989 Some planking replaced
- 1990 Reconstruction of bamboo gaff
- 1991 'Roof up' canvas sides replaced
- 1992 Insurance out-of-water survey  
Gas system fitted to new code of standard
- 1993 Decking recovered  
New 'tine lid' cover  
Boom jaws releathered
- 1994 Cockpit refitted
- 1995 Cabin roof resealed
- 1996 New forestay
- 1997 New winches
- 1998 New whisper pole  
New mainsail  
New bobstay
- 1999 New roof-up cover
- 2000 Condition survey report
- 2001 New mattresses
- 2002 Re-built tabernacle  
New bowsprit  
New side shrouds (2 - forward)  
New 'tine lid' cover
- 2003 Inboard engine and related hydraulics fitted  
Electric winch fitted for raising roof
- 2004 New gaff
- 2005 New cooker (to safety cut-off standard)  
Head outlet valve replaced
- 2006 Minor works associated with obtaining Boat Safety Certificate  
Replacement winches (Harken)  
Engine replaced with re-conditioned 6HP Petter  
Standing rigging checked over and some re-whipping
- 2007 BSS Certificate obtained (July)
- 2008 New over-mainsail boom cover  
New storm jib
- 2009 Replacement of two planks to starboard midships  
Engine alternator serviced (Panks)
- 2010 New top section to mast (from below cross trees)
- 2011 New no.2 jib  
Passed second BSS Certificate (expires 11/7/15)
- 2012 New stainless steel keel bolts
- 2013 Replacement of planking (30 foot run) and strengthening to three ribs to starboard/cockpit  
Engine overhaul (cylinder head)
- 2014 -
- 2015 Replacement of transom  
Replacement of both batteries - engine and domestic  
Passed 3<sup>rd</sup> BSS Certificate (expires 23/6/19)
- 2016 Some local patching of decking

**Current ownership (all at Phoenix Fleet Ltd. unless stated)**

- 2016 Reupholstered bunk mattresses (Haven upholstery)  
Repair to sail cover - small patch (Jeckells)  
Local varnish touching up  
Local deck patching  
Repainted interior deck and coach roof  
Refill and refinish stern hull planking joints  
New head and outlet seacock  
Replaced port halyard cheek block  
Refix rudder onto shaft
- 2017 Alternator retightened and connections replaced to reinstate battery charge (Ludham Bridge Boatyard - LBB)  
Toggle switch on engine cockpit control identified as on/off for alternator charge to battery (LBB)  
Engine service (LBB)
- 2018 New sail cover, repaired flat cover and reproofed awning (Jeckells)  
Replaced Peak, Throat and Jib halyards, Topping lift and Forestay line (Norfolk Marine)  
Decking replaced, new rubbers, rails and cants, tiller boss  
Varnish forepeak hatch, cabin sides  
Make good samson post and refix cleats