

Boatyard Condition Report

For acceptance by Yachtmaster Insurance Services Ltd

This form should only be completed by a boat builder or boatyard competent to undertake maintenance or repairs on this type of craft. The underwater hull must be fully sighted.

Owners Name:

Name of Vessel: Pirate

Length, Type and description: Broads River Cruiser
Sailing Yacht 29'3"

Please provide comment on the items listed below:

Hull Material: Oak planks on Oak frames

Hull/keel Condition: Good condition

Steering gear, shaft & Propeller(s): In good working order

Stanchions and deck fittings: All deck fittings secure in good order

Skin-fittings/sea-cocks: Bilge pump skin fitting is in good order

Bilge pump (electric and/or manual): Automatic electric bilge pump - working

Electrics System: 12v battery fitted with solar panel charger
powers LED nav lights, bilge pump & USB charger

Fire Extinguishers and fire blankets (number and type and if in test)
1 dry powder extinguisher in cockpit locker
- in date

Internal Condition: Good condition

Fuel tank and pipe work: N/A

Gas System (current boat safety scheme certificate) Yes/No Yes
(Please attach to this form if one available)

State of Gas system (pipes, fittings, gas lockers) N/A

Summary of findings and recommendations to bring boat up to a safe standard if applicable: The boat is in good working order

Report carried out by: Matt Ford Position: Boat Builder Date: 28/09/2021

Company Name: matt ford boatbuilding Signature: [Signature]